

Final Report Fenceline Response

Start Date & Time: 8/11/2018 10:15am

End Date & Time: 8/11/2018 10:25am

	Concentration (ppbv)	Wind Direction & Speed (MPH)
1	30.55	44 to 336 deg 1.8mph
2	46.17	262 to 327 deg 3.9mph
3	30.68	280 to 301 deg 7.2mph
4		

*Attach Additional pages of data if necessary

Potential Sources Identified: Operators conducted an investigation of the wind bin area and identified a leak on a pipeline to a neighboring facility.

Actions Taken to Reduce Emissions: TPC personnel isolated the leaking piing and prepared it for maintenance.

Reason No Action Was Taken: NA

Was a FLIR Camera Used to Identify Potential Sources? Yes No

Is there additional data attached? Yes No